VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 06-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   ward No - 03
2. Well Location : Sambram College opposite Temple Near
3. Total Well Depth / Drilled in Ft. : 1117 ft
4. Casing Erected in Ft. : 200 ft
5. Water Struck at the Depth of : 980 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 1000 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

15 HP / 30 Stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094

Mobile : +91 9342202932 | 9343202932

No. :

Date : 06-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward No-03
2. Well Location : Vijaya Bank layout #29 2
3. Total Well Depth / Drilled in Ft. : 1110 ft
4. Casing Erected in Ft. : 202 ft
5. Water Struck at the Depth of : 970 ft
6. Total Yield (Measuring method "V" North 3 inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 990 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

15 HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 06-05-2022

1. Customer's Name and Address With Telephone No. : Assistant Executive Engineer, Yelahanka division, ward no-03
2. Well Location : Jyothi Nagara
3. Total Well Depth / Drilled in Ft. : 1120 ft
4. Casing Erected in Ft. : 200 ft
5. Water Struck at the Depth of : 930 ft
6. Total Yield (Measuring method "V" North 3 inches / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear — clear
8. At the Depth of : 940
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

15 HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 06-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward no-03.
2. Well Location : Chowdappa Layout
3. Total Well Depth / Drilled in Ft. : 1118 ft
4. Casing Erected in Ft. : 192 ft
5. Water Struck at the Depth of : 980 ft
6. Total Yield (Measuring method "V" North 3 inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 1000 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

15 HP/ 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 07-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward No-03
2. Well Location : Aditya Nagara water tank Road
3. Total Well Depth / Drilled in Ft. : 1120 ft
4. Casing Erected in Ft. : 208 ft
5. Water Struck at the Depth of : 1000 ft
6. Total Yield (Measuring method "V" North 3 inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 1020 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

15 HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

Date : 07-05-2022

No. :

1. Customer's Name and Address With Telephone No. : Assistant Executive Engineer
   Yelahanka Division
   ward No-03.
2. Well Location : Balaji layout
3. Total Well Depth / Drilled in Ft. : 1117 ft
4. Casing Erected in Ft. : 192 ft
5. Water Struck at the Depth of : 990 ft
6. Total Yield (Measuring method "V" North 3 inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear
8. At the Depth of : 1000 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 HP / 30 Stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : Date : 08-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   ward No - 03
2. Well Location : ooty Convent School Road.
3. Total Well Depth / Drilled in Ft. : 1114 ft
4. Casing Erected in Ft. : 202 ft
5. Water Struck at the Depth of : 980 ft
6. Total Yield (Measuring method "V" North 3 inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : clear
8. At the Depth of : 1000 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

15 HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 28-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward No-03
2. Well Location : Near Allalsandra lake
3. Total Well Depth / Drilled in Ft. : 1117 ft
4. Casing Erected in Ft. : 199 ft
5. Water Struck at the Depth of : 990 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on "V" North
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 1010 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

   15 HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for any damage if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the completion report, I also fully understood the quality and quantity of the nature / formation of ground water and the drilling occurrence / Changes in the bore with full satisfaction. I hereby

Party's Signature

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 08-05-2022

1. Customer's Name and Address With Telephone No. : Assistant Executive Engineer
   Yelahanka Division
   ward no-03.
2. Well Location : Sai Nagara Phase-3
3. Total Well Depth / Drilled in Ft. : 1117 ft
4. Casing Erected in Ft. : 195 ft
5. Water Struck at the Depth of : 980 ft
6. Total Yield (Measuring method "V" North 3 inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear
8. At the Depth of : 1000 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

15 HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 09-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   ward No-03
2. Well Location : Viswanathanagara
3. Total Well Depth / Drilled in Ft. : 1114 ft
4. Casing Erected in Ft. :
5. Water Struck at the Depth of :
6. Total Yield (Measuring method "V" North — / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear
8. At the Depth of :
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 11-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward No-03
2. Well Location : Attur village, Govt school outside
3. Total Well Depth / Drilled in Ft. : 1120 ft
4. Casing Erected in Ft. :
5. Water Struck at the Depth of :
6. Total Yield (Measuring method "V" North _____ / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear
8. At the Depth of :
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 13-05-2022

1. Customer's Name and Address With Telephone No. : Assistant Executive Engineer, Yelahanka Division, Ward No-03.
2. Well Location : Attur village Govt School Inside
3. Total Well Depth / Drilled in Ft. : 1120 ft.
4. Casing Erected in Ft. :
5. Water Struck at the Depth of :
6. Total Yield (Measuring method "V" North _____ / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear
8. At the Depth of :
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094

Mobile : +91 9342202932 | 9343202932

No. :

Date : 13-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward No-03
   Re Drilling.
2. Well Location : AMS Layout, 2nd Cross
3. Total Well Depth / Drilled in Ft. : 1200 ft
4. Casing Erected in Ft. : 130 ft
5. Water Struck at the Depth of : 1080 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 1100 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 HP / 30 Stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 11-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward No-03
   Re Drilling
2. Well Location : Best County 2, 2nd main Road, Near Sai Baba temple
3. Total Well Depth / Drilled in Ft. : 1200 ft
4. Casing Erected in Ft. : 140 ft
5. Water Struck at the Depth of : 1050 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 1070 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 HP / 30 Stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 12-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Divisiom
   ward NO-03
   Re-Drilling
2. Well Location : Bettahalu min Road, Near Ambabavani Park
3. Total Well Depth / Drilled in Ft. : 1250 ft
4. Casing Erected in Ft. : 150 ft
5. Water Struck at the Depth of : 1120 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 1130 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence/ Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 06-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward No. 02.
2. Well Location : Shynik Vihar Layout, 8th main Road (Near ashram)
3. Total Well Depth / Drilled in Ft. : 1117 ft
4. Casing Erected in Ft. : 202 ft
5. Water Struck at the Depth of : 990 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 1010 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

15 HP / 30 Stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn.)
Yelahanka, Bangalore

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 06-05-2022

1. Customer's Name and Address With Telephone No. : Assistant Executive Engineer
   Yelahanka Division
   Ward No. 02
2. Well Location : Shyanik Vihar Layout, 6th main Road
3. Total Well Depth / Drilled in Ft. : 1114 ft
4. Casing Erected in Ft. : 200 ft
5. Water Struck at the Depth of : 1000 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear
8. At the Depth of : 1030 ft.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 Hp / 30 Stage.

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

AE-02 Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 06-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward No-02
2. Well Location : CRPF Residential Area Block No. A4
3. Total Well Depth / Drilled in Ft. : 1085 ft
4. Casing Erected in Ft. : 186 ft
5. Water Struck at the Depth of : 930 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 950 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

15 HP / 30 Stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

AE-02

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn.)
Yelahanka, Bangalore

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 06-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward No-02.
2. Well Location : Nagenahalli Layout 1st main Road
3. Total Well Depth / Drilled in Ft. : 1088 ft
4. Casing Erected in Ft. : 192 ft
5. Water Struck at the Depth of : 960 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 970 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

AE-02

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094

Mobile : +91 9342202932 | 9343202932

No. :

Date : 07-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward No-02.
2. Well Location : Nagenahalli Layout Near Railway Track
3. Total Well Depth / Drilled in Ft. : 1095 ft
4. Casing Erected in Ft. : 195 ft
5. Water Struck at the Depth of : 980 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 1000 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

For VINAYAKA ENTERPRISES

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 07-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   ward No-02.
2. Well Location : Near Doctor house Suryavamshi Layout
3. Total Well Depth / Drilled in Ft. : 1110 ft
4. Casing Erected in Ft. : 201 ft
5. Water Struck at the Depth of : 960 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear clear
8. At the Depth of : 980 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

AE-02 Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

For VINAYAKA ENTERPRISES

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 08-05-2022

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward No-02.
2. Well Location : Suryavamshi Layout 1st main Road
3. Total Well Depth / Drilled in Ft. : 1088 ft
4. Casing Erected in Ft. : 190 ft
5. Water Struck at the Depth of : 950 ft
6. Total Yield (Measuring method "V" North 25 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear
8. At the Depth of : 970 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 HP / 30 stage.

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

For VINAYAKA ENTERPRISES

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 08-05-2022

1. Customer's Name and Address With Telephone No. : Assistant Executive Engineer, Yelahanka Division, ward No - 02.
2. Well Location : Near Nagenahalli Gundtopu
3. Total Well Depth / Drilled in Ft. : 1118 ft
4. Casing Erected in Ft. : 186 ft
5. Water Struck at the Depth of : 920 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear
8. At the Depth of : 940 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

For VINAYAKA ENTERPRISES

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 09-05-22

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   ward No-02.
2. Well Location : Near Nagesh House ISRO Layout.
3. Total Well Depth / Drilled in Ft. : 1110 ft
4. Casing Erected in Ft. : 190 ft
5. Water Struck at the Depth of : 930 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear
8. At the Depth of : 960 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 09-05-22

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   ward No-02.
2. Well Location : ISRO Layout 1st main Road
3. Total Well Depth / Drilled in Ft. : 1105 ft
4. Casing Erected in Ft. : 202 ft
5. Water Struck at the Depth of : 970 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear
8. At the Depth of : 1000 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 HP / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 10-5-22

1. Customer's Name and Address With Telephone No. : Assistant Executive Engineer
   Yelahanka Division
   Ward No. 02.
2. Well Location : Naidu layout, Near Gangamma Temple
3. Total Well Depth / Drilled in Ft. : 1104 ft
4. Casing Erected in Ft. : 205 ft
5. Water Struck at the Depth of : 960 ft
6. Total Yield (Measuring method "V" North 2.5 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear
8. At the Depth of : 990 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 Hp / 30 stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn.)
Yelahanka, Bangalore

For VINAYAKA ENTERPRISES

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 11-05-22

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Yelahanka Division
   Ward No- 02.
2. Well Location : Srinidhi Layout 1st main Road.
3. Total Well Depth / Drilled in Ft. : 1115 ft
4. Casing Erected in Ft. : 202 ft
5. Water Struck at the Depth of : 1000 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 1030 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15HP / 30 Stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

Asst. Executive Engineer
Yelahanka Sub Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

For VINAYAKA ENTERPRISES

Manager / Proprietor

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 11-05-22

1. Customer's Name and Address With Telephone No. : Assistant Executive Engineer
   Yelahanka Division
   Ward No. 02.
2. Well Location : Harohalli village 6th A Cross Road
3. Total Well Depth / Drilled in Ft. : 1117 ft
4. Casing Erected in Ft. : 205 ft
5. Water Struck at the Depth of : 980 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear
8. At the Depth of : 1000 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 HP / 30 Stage

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. :

Date : 13-05-22

1. Customer's Name and Address With Telephone No. : Assistant Executive Engineer
   Yelahanka Division
   Ward No. 02.
2. Well Location : Kenchenahalli Prakruthi Layout 5th A Cross
3. Total Well Depth / Drilled in Ft. : 1114 ft
4. Casing Erected in Ft. : 208 ft
5. Water Struck at the Depth of : 980 ft
6. Total Yield (Measuring method "V" North 3 Inches / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear
8. At the Depth of : 1000 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump
   15 HP / 30 Stage.

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

For VINAYAKA ENTERPRISES

Manager / Proprietor